## Approved For Release 2003/01/17: CIA-RDP78B04747A000400030016-8

6 June 1967 TO: STAT SUBJECT: Aerial Film STAT STAT We experienced a problem with film when we attempted to STAT process through the processor Both machines STAT had a breakdown, result - broken gears, etc. This apparently was due to the slick backing on the film which caused tracking problems. On November 29, 1966 the Quality Control Staff ran a test simi-**STAT** lar to the test and as a result of our tests we would agree with their finding. However, again, it was a controlled STAT laboratory test and not a production run. We use for the duplication of all Satellite missions, all other mission type work is STAT printed on unless a higher resolution is called for, and at this STAT time we would use **STAT** is slightly better Resolution and not as good STAT Material tested was 4 mils. We would be interested in trying STAT the 7 mils STAT STAT

**Declass Review by NIMA / DoD**